

**URGENT NAVICOM RT-650 AIS SOFTWARE UPDATE**

Reference Navicom RT-650 & RT-650WR AIS Reception

Known software issue affecting software versions prior to 2.00

On the AIS readout of target vessels displayed on the RT-650, the Length, Beam and Heading of the vessel is shown numerically incorrect with the decimal point being shifted one place to the left, thus a vessel of 200m long is shown as 20.0m long and its heading shown as 3.0 degrees is actually 30 degrees.

A new software version 2.00 is available to correct this error, please contact the retailer you purchased the radio from for update advice. If they are a Service Dealer they may be able to update the software on site or alternatively the RT-650 may be returned to Mantsbrite for the software update, we will return it direct to the end user free of charge. Turnaround time will be in the order of 3 – 4 working days.

The Maritime and Coast Guard Agency are aware of this problem and of the action being taken by Mantsbrite.

We regret any inconvenience that this may cause to you or your customers and please be assured that we are taking all practical steps to replace the software of the relatively low number of equipments involved as quickly as possible.

Thank you for your attention to this matter.

If you are returning your RT-650 directly to us please address it to:

Product Support  
Mantsbrite Limited  
19F Spital Road  
Maldon  
Essex CM9 6DY  
United Kingdom

Tel: + 44 (0) 1621 853003